

FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

DISCHARGE OF UNTREATED WASTEWATER

UTILITY CO./OWNER: South Seminole & North Orange County Wastewater Transmission Authority PHONE: (407) 628-3419
 LOCATION, LIFT STATION, MANHOLE Air Release Valve – 4200 Dike Road, Winter Park, FL 32792
 REPORTED DATE: 6-08-2017 TIME 6:30 PM BY: Eric Gassen
 DISCHARGE STARTED: 6-08-2017 TIME 8:00 AM STOPPED DATE: 6-08-2017 TIME 9:00 AM
 CLASSIFICATION: MAJOR X MINOR _____ APPROX VOLUME OR RATE: 2,000 gallons

SURFACE WATERS (lake, stream, storm drain) has or will overflow enter surface water?

YES _____ NO X POSSIBLY _____

If yes, identify surface water and distance from overflow site _____

CAUSE:

While performing routine maintenance on and Air Release Valve (ARV) – the isolation valve was not closed before the ARV was opened
which allowed the flow from the force main to travel up the 2" riser pipe and spill into the street. The valves were in a vault which
immediately filled with wastewater and did not allow for the safe closer of the isolation valve.

CORRECTIVE and/or SAFETY MEASURES INITIATED:

Vac trucks were immediately sent to the site to drain the vault and siphon flow from the open line until the isolation valve could be
closed stopping the flow.

REPORTED OVERFLOW TO: F.D.E.P. X HEALTH DEPT. _____
 Florida Department of Environmental Protection Phone: (800) 320-0519 Fax: (407) 893-3166

NOTE: Above information should be provided when making initial verbal report.

The information above and below should be completed and submitted to the Florida Department of Environmental Protection within three (3) work days after overflow occurred.

WHAT ADDITIONAL MEASURES WERE TAKEN TO PROTECT SURFACE WATERS AND PUBLIC HEALTH?

Excess flow was siphoned using a vac truck so that the spill would not spread. The spill was contained primarily to the roadway and side of
the road and had no immediate impact to the public.

WHAT CLEAN-UP MEASURES WERE TAKEN?

The vac truck was used to suck up the water that was spilled. The roadway was treated with chlorine and all grass areas were treated with
lime as a disinfectant.

PLANS TO PREVENT REOCCURRENCE:

Greater care will be taken to ensure all safety procedures are followed while maintaining the ARVs. A safety meeting was held with the
maintenance contractor to discuss ARV maintenance protocol.

ADDITIONAL REMARKS:

REPORTED BY:

Eric Gassen
 Signature